


MOUNTING KITS



Part Number 8450-1 Gate Mounting Kit Consists of:

- 1 S4402-A SPDT Switch
- 1 M-4400 Magnet
- 2 S-201 Brackets
- 4 #6-32 x 5/16 Zinc Hex Nuts
- 4 #6 External Lock Washers
- 4 #6-32 x 3/4 Phillips Machine Screws
- 2 #8 x 1 Self Tap Combo Panhead Type A Screws

Part Number 8450-2 Gate Mounting Kit Consists of:

- 1 S4402-A SPDT Switch
- 1 M-4400 Magnet
- 2 S-202 Brackets
- 4 #6-32 x 5/16 Zinc Hex Nuts
- 4 #6 External Lock Washers
- 4 #6-32 x 3/4 Phillips Machine Screws
- 2 #8 x 1 Self Tap Combo Panhead Type A Screws

Part Number 8450-3 Gate Mounting Kit Consists of:

- 1 S4402-A SPDT Switch
- 1 M-4400 Magnet
- 1 S-202 Bracket
- 1 S-201 Bracket
- 4 #6-32 x 5/16 Zinc Hex Nuts
- 4 #6 External Lock Washers
- 4 #6-32 x 3/4 Phillips Machine Screws
- 2 #8 x 1 Self Tap Combo Panhead Type A Screws

GEORGE RISK INDUSTRIES, INC.
G.R.I. PLAZA
KIMBALL, NE 69145



TOLL-FREE 1-800-445-5218
TOLL-FREE 1-800-523-1227
(308) 235-4645
FAX (308) 235-3561
E-MAIL: grisales@megavision.com
WEB SITE: www.grisk.com